



LADA



REPLACEMENT FOR

2105/2106/2107 '83-'88

REPLACEMENT FOR

2108 SAMARA '86-'90

662-1104-LD 2105 43T
 HEAD LAMP
 R 2105-3711010-10
 L 2105-3711011-10
 6PCS 5.60CFT



H4

662-1103-LD 2107 43T
 HEAD LAMP LD:
 RD: R 2107-3711010-11
 R 2107-3711010-10 L 2107-3711011-11
 L 2107-3711011-10 4PCS 5.60CFT



H4

662-1101-LDEHU 43T
 HEAD LAMP
 R
 L
 6PCS 6.28CFT



H4/T4W/P21W

662-1401
 SIDE LAMP
 R
 L
 PCS CFT



W5W TBA



662-1101-LD-E 43T
 HEAD LAMP
 R 2108-3711010-01
 L 2108-3711011-01
 6PCS 6.28CFT



H4/T4W

662-1902 2105
 TAIL LAMP
 R
 L
 10PCS CFT



TBA

662-1901 2107
 TAIL LAMP
 R
 L
 PCS CFT



21W/4W TBA

662-1501-UE
 CORNER LAMP
 R
 L
 20PCS 1.89CFT



P21W

662-1903 NIVA 1600CC 2106
 TAIL LAMP
 R 2105-3716010-01
 L 2105-3716011-01
 PCS CFT




TBA



662-1910 2104
 TAIL LAMP
 R
 L
 PCS CFT



TBA





REPLACEMENT FOR

2110/2112 '02



REPLACEMENT FOR

2115 '00

662-1105-LD

HEAD LAMP
R 0301050014
L 0301050013
PCS
CFT



H1/H1/W5W

TBA

662-1106-LD

HEAD LAMP
R
L
PCS
CFT



H4/W5W

TBA

662-1502-UE

CORNER LAMP
R 0315106938
L 0315106937
PCS
CFT



PY21W

TBA

662-1503

CORNER LAMP
R
L
PCS
CFT



P21W

TBA

662-1906

TAIL LAMP
R
L
PCS CFT



P21W

TBA

662-1301

BACK LAMP
R
L
PCS CFT



P21W

TBA



LADA